



Webinar:

Working and
Programming with CAD
Import

HEIDENHAIN

Instructor: Michael Wiendl



Company: Dr. Johannes
HEIDENHAIN GmbH

Position: Trainer for NC
Programming



CAD import

- Fundamentals
- Specifying the workpiece preset
- Selecting the datum
- Selecting contours
- Selecting machining positions

Programming

- Open contour
- Closed contour
- Machining positions
- Datum shift and tilting the working plane



Tips and Tricks

- Navigation
- Contour transfer
- Path optimization
- TNC Club






CAD import






CAD Import





CAD viewer


- Standard (not an option)
 - TNC 640 as of NC SW 34059x-05
 - TNC 620 as of NC SW 81760x-02
 - TNC 320 as of NC SW 771851-01
-
- Software option 98
 - iTNC 530 as of 60642x-02/34049x-07
-
- Opening STEP, IGES, and DXF files
 - Viewer for 3-D models
 - Display of element information





DXF converter


- Software option 42
 - TNC 640 as of NC SW 34059x-02
 - TNC 620 as of NC SW 73498x-02/81760x-01
 - TNC 320 as of NC SW 771851-01
 - iTNC 530 as of 60642x-01/34049x-02
-
- Opening DXF files on the control
 - Selecting machining positions and contours from the DXF file





CAD import

- Software option 42
 - TNC 640 as of NC SW 34059x-08
 - TNC 620 as of NC SW 81760x-05
 - TNC 320 as of NC SW 77185x-05
-
- Opening of 3-D models (STEP/IGES) on the control
 - Opening DXF files continues to be possible
 - Defining the datum and the tilted working plane directly from the 3-D model
 - Selecting machining positions and contours from the 3-D model






Specifying the workpiece preset

- The designer specifies the workpiece preset (position of the coordinate system) of the 3-D model in the CAD system
- The preset for machining and the preset of the design often do not correspond to each other

Procedure:



- Activate presetting
- Adjust the preset by means of three points
 - The first point defines the origin of the coordinate system
 - The second point defines the positive X axis
 - The third point defines the positive Y axis







Specifying the workpiece preset



- The designer specifies the workpiece preset (position of the coordinate system) of the 3-D model in the CAD system
- The preset for machining and the preset of the design often do not correspond to each other

Procedure:


- Activate presetting 
- Adjust the preset by means of three points
 - The first point defines the origin of the coordinate system
 - The second point defines the positive X axis
 - The third point defines the positive Y axis

Result:

- The workpiece preset is set 
- All other actions refer to this preset



Preset	
X	8.0000
Y	-38.0776
Z	8.0000
PLANE SPATIAL SP*	
A	0.0000
B	0.0000
C	90.0000








Preset

M-TS / May 2018

Deleting the preset / RESET

- Reset the preset with 






Datum and Tilting the Working Plane


M-TS / May 2018

Datum and tilting the working plane

- For machining, you now define the datum and, if required, also the angles for tilting the working plane

Procedure:

- Activate the datum 
- Adjust the preset by means of three points
 - The first point defines the origin of the coordinate system (datum)
 - The second point defines the positive X axis
 - The third point defines the positive Y axis






Datum and Tilting the Working Plane

M-TS / May 2018

Datum and tilting the working plane




- For machining, you now define the datum and, if required, also the angles for tilting the working plane

Procedure:

- Activate the datum 
- Adjust the preset by means of three points
 - The first point defines the origin of the coordinate system (datum)
 - The second point defines the positive X axis
 - The third point defines the positive Y axis

Result:

- The datum is set 
- Select contours or machining positions based on this datum








Datum and Tilting the Working Plane

M-TS / May 2018

Program output

- Save  the datum shift and the tilted working plane in a Klartext conversational program.
- Copy  the datum shift and the tilted working plane to the buffer memory. Insert them into the NC program with INSERT BLOCK.



→ TILT1.H



```
0 BEGIN PGM TILT1 MM
1 ;* origin_file = "Stem0.stp"
2 ;* origin = X+0.0000 Y+.0000 Z+22.5000
3 ;* origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
4 PLANE RESET STAY
5 TRANS DATUM AXIS X+11.7652 Y-19.7147 Z-38.3685
6 PLANE SPATIAL SPA+90 SPB+0 SPC-8.339 TURN MB MAX FMAX
7 END PGM TILT1 MM
```




Datum and Tilting the Working Plane

M-TS / May 2018

Program output

- Save  the datum shift and the tilted working plane in a Klartext conversational program.
- Copy  the datum shift and the tilted working plane to the buffer memory. Insert them into the NC program with INSERT BLOCK.



→ TILT1.H



```
0 BEGIN PGM TILT1 MM
1 ;* origin_file = "Stem05.stp"
2 ;* origin = X+0.0000 Y+0.0000 Z+22.5000
3 ;* origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
4 PLANE RESET STAY
5 TRANS DATUM AXES X+11.7852 Y-19.7147 Z 22.5000
6 PLANE SPATIAL SPA+90 SPB+0 SPC-8.339 TURN MB MAX FMAX
7 END PGM TILT1 MM
```





Datum and Tilting the Working Plane

M-TS / May 2018

Deleting the datum and working plane tilt / RESET


- Reset your selection with 
- Undo the last step with 





Selecting contours

- Transferring a continuous contour with two mouse clicks:
 - Click the first element (consider the direction → arrow)
 - Click the last element








Selecting contours




- Transferring a continuous contour with two mouse clicks:
 - Click the first element (consider the direction → arrow)
 - Click the last element

Procedure:

- Activate contour selection 
- Select a contour

Program output

- Save  the contour in a Klartext conversational program.
- Copy  the contour to the buffer memory. Insert it into the NC program with INSERT BLOCK.








Selecting contours

- Transferring a continuous contour with two mouse clicks:
 - Click the first element (consider the direction → arrow)
 - Click the last element

Procedure:

- Activate contour selection 
- Select a contour

Program output

- Save  the contour in a Klartext conversational program.
- Copy  the contour to the buffer memory. Insert it into the NC program with INSERT BLOCK.

```
→ CONTOUR1.H
0 BEGIN PGM CONTOUR1 MM
1 * 8 contours
2 ;* origin_file = "Stem05.stp"
3 ; FUNCTION MODE MILL
4 ;* origin = X+0.0000 Y+0.0000 Z+22.5000
5 ;* origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
6 ; PLANE RESET STAY
7 ; TRANS DATUM AXIS X+11.7652 Y-19.7147 Z-38.3685
8 ; PLANE SPATIAL SPA+90.0000 SPB+0.0000 SPC-8.3390 TURN MB MAX FMAX
9 ; 1 + 3 line(s) + 5 arc(s) + 0 gap-filler(s), minimum arc radius = +4.2500
10 ; all_blk_form from complete file
11 BLK FORM 0.1 Z X-22.223 Y-24 Z-22.5
12 BLK FORM 0.2 X+70.9 Y+24 Z+22.5
13 ; sel_blk_form from selection
14 BLK FORM 0.1 Z X-4.5 Y-42.648 Z-11.6185
15 BLK FORM 0.2 X+66.3317 Y+31.737 Z+11.6185
16 L X+0 Y+0 Z+0
17 L X+19.0759 Y+0 Z+0
18 CC X+19.0759 Y+4.25
19 C X+22.6687 Y+6.5203 DR+
20 CC X+37.4627 Y+15.8685
21 C X+22.6687 Y+25.2168 DR-
22 CC X+19.0759 Y+27.487
23 C X+19.0759 Y+31.737 DR+
24 L X+0 Y+31.737 Z+0
25 CC X+0 Y+27.237
26 C X-4.5 Y+27.237 DR+
27 L X-4.5 Y+4.5 Z+0
28 CC X+0 Y+4.5
29 C X+0 Y+0 DR+
30 ;* end contours
31 END PGM CONTOUR1 MM
```



Selecting Machining Positions


M-TS / May 2018

Selecting machining positions

- Click the elements
- Sequence for clicking = machining sequence

Procedure:

- Activate position selection
- Select positions





Selecting Machining Positions

M-TS / May 2018

Selecting machining positions



- Click the elements
- Sequence for clicking = machining sequence


Procedure:

- Activate position selection
- Select positions



Program output

- Save  the positions in a point table.
- Copy  the positions to the buffer memory. Insert them into the NC program with INSERT BLOCK.





Selecting Machining Positions

M-TS / May 2018

Selecting machining positions



- Click the elements
- Sequence for clicking = machining sequence

Procedure:

- Activate position selection
- Select positions



Program output

- Save  the positions in a point table
- Copy  the positions to the buffer memory. Insert them into the NC program with INSERT BLOCK.

NR	X	Y	Z	FADE	CLEARANCE
0	0.0000	-0.0000	0.0000	N	
1	36.0000	-0.0000	0.0000	N	
2	36.0000	-37.7370	0.0000	N	
3	0.0000	-37.7370	0.0000	N	

Point table .PNT

```
→ CONTOUR1.H
36 ; PLANE RESET STAY
37 ; TRANS DATUM AXIS X+59.1453 Y-18.0000 Z-3.6315
38 ; PLANE SPATIAL SPA+90.0000 SPB+0.0000 SPC+90.0000 TURN MB MAX FMAX
39 ; BLK FORM 0.1 Z X+59.1203 Y-18.0000 Z-18.8685
40 ; BLK FORM 0.2 X+59.1703 Y+18.0000 Z+18.8685
41 L X+0 Y+0 Z+0 FMAX M99
42 L X+36 Y+0 Z+0 FMAX M99
43 L X+36 Y-37.737 Z+0 FMAX M99
44 L X+0 Y-37.737 Z+0 FMAX M99
45 ; * end positions
```



NC program .H



Open contour

- Integrating the contour into the NC program:
 - SEL CONTOUR with the path for contour description
- or
- Cycle 14 with contour label



- Machining with
 - Cycle 25 with definition of
 - DEPTH
 - INFEEED
 - Residual material can also be reworked, if required
 - Define the type of approach with Cycle 270





Closed contour

- Rough-out with SL cycles. Nesting of contours with
 - CONTOUR DEF with the path for contour description and definition of island/pocket (up to nine contours are possible)
 - or
 - Cycle 14 with contour labels (up to twelve contours are possible)
 - or
 - Complex contour formula (up to 128 contours are possible)
-
- Machining with
 - Cycle 20 (Contour data)
 - Cycle 21 (Pilot drilling, optional)
 - Cycle 22 (Roughing)
 - Cycle 23 (Floor finishing, optional)
 - Cycle 24 (Side finishing, optional)





Machining positions

- Integrating the point table into the NC program with SEL PATTERN
- Machining with fixed cycles (e.g. Cycle 200)
- Calling the programmed machining cycle at any position from the point table with CYCL CALL PAT

```
TNC:\Webinar_CAD-Viewer\PGM.h
->PGM.h
33 CALL LBL 102
34 :
35 : ' origin_file = "Stew05.stp"
36 : ' origin = X+0.0000 Y+0.0000 Z+22.5000
37 : ' origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
38 PLANE RESET STAY
39 TRANS DATUM AXIS X=30.6394 Y=22.4813 Z=38.3685
40 CALL LBL 100
41 PLANE SPATIAL SPA+90 SPB+0 SPC-171.6609 TURN FMAX
42 CONTOUR DEF
  PT = "TNC:\Webinar_M12\010_CAD-Viewer\lilted_pocket4.H"
43 L X+0 Y+0 Z+100 R0 FMAX M99
44 CALL LBL 101
45 :
46 : ' origin_file = "Stew05.stp"
47 : ' origin = X+0.0000 Y+0.0000 Z+22.5000
48 : ' origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
49 PLANE RESET STAY
50 TRANS DATUM AXIS X=18.223 Y=6.5 Z=5
51 CALL LBL 100
52 PLANE SPATIAL SPA+90 SPB+0 SPC+0 TURN FMAX
53 SEL PATTERN "TNC:\Webinar_M12\010_CAD-Viewer\post1.PMT"
54 CYCL DEF 208 BORE MILLING
  0200+2 :SET-UP CLEARANCE
  0201-7 :DEPTH
  0206+150 :FEED RATE FOR PLNGNG
  0334+0.25 :PLUNGING DEPTH
  0203+7 :SURFACE COORDINATE
  0204+50 :2ND SET-UP CLEARANCE
  0335+9 :NOMINAL DIAMETER
  0342+0 :ROUGHING DIAMETER
  0351+1 :CLIMB OR UP-CUT
55 L X+0 Y+0 Z+100 R0 FMAX
```

```
TNC:\Webinar_CAD-Viewer\PGM.h
->PGM.h
43 L X+0 Y+0 Z+100 R0 FMAX M99
44 CALL LBL 101
45 :
46 : ' origin_file = "Stew05.stp"
47 : ' origin = X+0.0000 Y+0.0000 Z+22.5000
48 : ' origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
49 PLANE RESET STAY
50 TRANS DATUM AXIS X=18.223 Y=6.5 Z=5
51 CALL LBL 100
52 PLANE SPATIAL SPA+90 SPB+0 SPC+0 TURN FMAX
53 SEL PATTERN "TNC:\Webinar_M12\010_CAD-Viewer\post1.PMT"
54 CYCL DEF 208 BORE MILLING
  0200+2 :SET-UP CLEARANCE
  0201-7 :DEPTH
  0206+150 :FEED RATE FOR PLNGNG
  0334+0.25 :PLUNGING DEPTH
  0203+7 :SURFACE COORDINATE
  0204+50 :2ND SET-UP CLEARANCE
  0335+9 :NOMINAL DIAMETER
  0342+0 :ROUGHING DIAMETER
  0351+1 :CLIMB OR UP-CUT
55 L X+0 Y+0 Z+100 R0 FMAX
56 CYCL CALL PAT FMAX
57 CALL LBL 101
58 :
59 * End machining
60 *-----
61 CALL LBL 101
62 M99
63 * SAFE POS LBL 100
64 LBL 100 :SAFE POS
65 CALL PGM TNC:\SAFE.H
66 LBL 0
```




Datum shift and tilting the working plane

- Direct insertion into the NC program with INSERT BLOCK
 - PLANE RESET STAY
 - TRANS DATUM
 - PLANE SPATIAL (CAUTION, the default setting here is MB MAX; this may have to be adjusted)

```
TNC:\Webinar_CAD-Viewer\PGM_h
- PGM_h
019- AUTO : FEED RATE FOR RECIP.
0208- MAX : RETRACTION FEED RATE
0401-+100 : FEED RATE FACTOR
0404-+0 : FINE ROUGH STRATEGY
31 L X=0 Y=0 Z=100 R0 FMAX
32 M99
33 CALL LBL 102
34 :
35 : ' origin_file = "Stem05.stp"
36 : ' origin = X+0.0000 Y+0.0000 Z+22.5000
37 : ' origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
38 PLANE RESET STAY
39 TRANS DATUM AXIS X+30.6394 Y+22.4813 Z-38.3685
40 CALL LBL 100
41 PLANE SPATIAL SPA+90 SPB+0 SPC-171.6609 TURN FMAX
42 CONTOUR DEF
P1 = "TNC:\Webinar_M12\010_CAD-Viewer\tilted_pocket4.H"
43 L X=0 Y=0 Z=100 R0 FMAX M99
44 CALL LBL 101
45 :
46 : ' origin_file = "Stem05.stp"
47 : ' origin = X+0.0000 Y+0.0000 Z+22.5000
48 : ' origin_plane_spatial = SPA+0.0000 SPB+0.0000 SPC+0.0000
49 PLANE RESET STAY
50 TRANS DATUM AXIS X 18.223 Y 6.5 Z 5
51 CALL LBL 100
52 PLANE SPATIAL SPA+90 SPB+0 SPC+0 TURN FMAX
53 SEL PATTERN "TNC:\Webinar_M12\010_CAD-Viewer\post1.PMT"
54 CYCL DEF 208 BORE MILLING
0200=+2 :SET-UP CLEARANCE
0201=-7 :DEPTH
0206=+150 :FEED RATE FOR PLUNGING
0334=+0.25 :PLUNGING DEPTH
```






Tips and Tricks





Quick switchover between CAD import and programming

- Open CAD import on the third desktop, so that you can leave it open during programming
- Use the toggle key for fast switchover






Tolerance for Contour Transfer

M-TS / May 2018

Available in contour transfer mode







- Define the tolerance for how far neighboring elements should be from each other
- Compensating inaccuracy





Selecting and deselecting

- Select elements with the mouse pointer 
- Display additional points with  (show start point, center point and end point)
- Deselect elements with 








Path Optimization

M-TS / May 2018




Available only in point transfer mode

- Click the positions
- Sort the positions with the path optimization function 
- Clicking sequence shown in **RED**
- Positions after path optimization shown in **GREEN**





Program output

- Set the program output with 
- Output with XYZ coordinates 
- Output with XY coordinates 

```
L X+0 Y+0 Z+0
CC X+0 Y+4.5
C X-4.5 Y+4.5 DR-
L X-4.5 Y+27.237 Z+0
CC X+0 Y+27.237
C X+0 Y+31.737 DR-
L X+19.0759 Y+31.737 Z+0
CC X+19.0759 Y+27.487
C X+22.6687 Y+25.2168 DR-
CC X+37.4627 Y+15.8685
C X+22.6687 Y+6.5203 DR+
CC X+19.0759 Y+4.25
C X+19.0759 Y+0 DR-
L X+0 Y+0 Z+0
```

```
L X+0 Y+0
CC X+0 Y+4.5
C X-4.5 Y+4.5 DR-
L X-4.5 Y+27.237
CC X+0 Y+27.237
C X+0 Y+31.737 DR-
L X+19.0759 Y+31.737
CC X+19.0759 Y+27.487
C X+22.6687 Y+25.2168 DR-
CC X+37.4627 Y+15.8685
C X+22.6687 Y+6.5203 DR+
CC X+19.0759 Y+4.25
C X+19.0759 Y+0 DR-
L X+0 Y+0
```



Any questions?

Tel.: +49 8669 31-3103

**E-mail:
3103@heidenhain.de**

HEIDENHAIN

**Thank you very much for
your attention!**

Michael Wiendl

